QUANTITY

UNITS

CAT CODE


800000

DESCRIPTION

CONTROLLER

PHASE CHART

PHASE 2 AND 6	G	G	G	G	R	R	R	R	R	R	WK	WK	WK	WK	DW	DW	00
PED CLEARANCE	G	G	G	G	R	R	R	R	R	R	FL/DW	FL/DW	FL/DW	FL/DW	DW	DW	
2 AND 6 CHANGE	Υ	Υ	Υ	Y	R	R	R	R	R	R	DW	DW	DW	DW	DW	DW	00
PHASE 4 AND 8	R	R	R	R	G	G	G	G	G	G	DW	DW	DW	DW	DW	DW	<u></u>
4 AND 8 CHANGE	R	R	R	R	Υ	Υ	Υ	Υ	Υ	Y	DW	DW	DW	DW	DW	DW]
PHASE 4 ALT & 8	R	R	R	R	G	G	G	G	G	G	DW	DW	DW	DW	WK	WK	
PED CLEARANCE	R	R	R	R	G	G	G	G	G	G	DW	DW	DW	DW	FL/DW	FL/DW	
4 ALT & 8 CHANGE	R	R	R	R	Y	Y	Υ	Υ.	Υ	Υ	DW	DW	DW	DW	DW	DW)
FLASHING OPERATION	FLY	FL/Y	FL/Y	FLY	FL/R	FL/R	FL/R	FL⁄R	FL/R	FL⁄R	DARK	DARK	DARK	DARK	DARK	DARK	Δ ∇ D



SABRA,WANG & ASSOCIATES, INC

1504 JOH AVENUE

SUITE 160

BALTIMORE, MD 21227

(410) 737-6564

WWW.SABRA-WANG.COM

OPTIC CABLE.

7. POLE MOUNTED SPLICE CABINETS SHALL BE INSTALLED

INTERCONNECT CABLE SPLICES SHALL BE WITH 3"

RISERS AND WEATHER HEADS, NO STRAND MOUNTED

OR AERIAL CLOSURE WILL BE ACCEPTED.

AT GROUND WORKING HEIGHT, SPLICE CLOSURE FOR

DRAWN BY

F.A.P. NO.

CHECKED BY

TS NO. 437 B

DESIGNED BY _____AZORETIC

A.ZORETIC

DRAWING pSG OF

K.RINIKER

MONTGOMERY

SHEET NO. 34H OF 56F

15009705.58

COUNTY ___

LOGMILE _

TOD NO.

T.I.M.S. NO. <u>J203</u>